ALVORD AND ALVORD

ATTORNEYS AT LAW

1050 SEVENTEENTH STREET, N.W.

SUITE 301

Washington, D.C.

ELIAS C. ALVORD (1942) ELLSWORTH C. ALVORD (1964) 20036

OF COUNSEL URBAN A. LESTER

October 29, 2002

(202) 393-2266

FAX (202) 393-2156

E-MAIL alvordlaw@aol.com

Mr. Vernon A. Williams Secretary Surface Transportation Board Washington, D.C. 20423 RECORDATION NO. 24190 FILE

OCT 2 9 '02

3-11 PM

Dear Mr. Williams:

is:

SURFACE TRANSPORTATION BOARD

Enclosed for recordation pursuant to the provisions of 49 U.S.C. Section 11301(a) are two (2) copies of a Memorandum of Security Agreement, dated as of October 28, 2002, a primary document as defined in the Board's Rules for the Recordation of Documents.

The names and addresses of the parties to the enclosed document are:

Borrower:

Trinity Rail Leasing Trust II 2525 Stemmons Freeway

Dallas, Texas 75207

Secured Party:

Credit Suisse First Boston,

New York Branch

Eleven Madison Avenue New York, NY 10010

A description of the railroad equipment covered by the enclosed document

465 railcars bearing ACTX, ARJX, TILX and TIMX reporting marks and road numbers.

Mr. Vernon A. Williams October 29, 2002 Page Two

A short summary of the document to appear in the index follows:

Memorandum of Security Agreement.

Also enclosed is a check in the amount of \$30.00 payable to the order of the Surface Transportation Board covering the required recordation fee.

Kindly return stamped copies of the enclosed document to the undersigned.

Very truly yours,

Robert W. Alvord

RWA/anr Enclosures

MEMORANDUM OF SECURITY AGREEMENT

This Memorandum of Security Agreement (this "Memorandum") is executed as of 28th of October, 2002, by and between TRINITY RAIL LEASING TRUST II, a Delaware business trust (the "Borrower") and CREDIT SUISSE FIRST BOSTON, NEW YORK BRANCH, as Agent for the Secured Parties (as defined in the Security Agreement, as defined below).

The Borrower and the Agent have entered into a Security Agreement dated as of June 27, 2002 (as from time to time amended, modified or supplemented, the "Security Agreement") by which the Borrower has granted a security interest to the Agent for the ratable benefit of the Secured Parties (as defined in the Security Agreement) in all assets of the Borrower, including without limitation, certain railroad equipment described on and bearing reporting marks and road numbers as provided on Exhibit A (the "Railcars") and certain leases relating to such Railcars as described on Exhibit B (the "Leases"), whether now owned or hereafter arising or acquired.

The purpose of this Memorandum is to give record notice of the existence of the security interest of the Agent in the Railcars and the Leases, and all terms and conditions of the Security Agreement are incorporated by reference herein.

This Memorandum is prepared only for the public record and is being recorded with the Surface Transportation Board pursuant to 49 U.S.C. 11301(a) and the Registrar General of Canada.

[signature page to follow]

RECORDATION NO. 24190 FILED

OCT 2 9 '02 3-11 PM

SURFACE TRANSPORTATION BOARD

IN WITNESS WHEREOF, the undersigned has caused this Memorandum to be executed by a duly authorized officer as of the day and year first above written.

TRINITY RAIL LEASING TRUST II

Name: Eric Marchetto

Title: Vice President

CREDIT SUISSE FIRST BOSTON, NEW YORK BRANCH

By:

Name: Mark Lengel

Vice President

CREDIT SUISSE FIRST BOSTON, NEW YORK BRANCH

By:

Name Joseph Soave

Vice President

ACKNOWLEDGMENT

STATE OF	Texas	
COUNTY OF	Dallas	

BEFORE ME, a Notary Public of the State and County aforesaid, personally appeared Eric Marchetto, who upon oath, acknowledged himself to be a vice president of TRINITY RAIL LEASING TRUST II, a Delaware business trust, and that s/he as such officer being authorized to do so, executed the foregoing Memorandum of Security Agreement for the purposes therein contained by signing the name of the Delaware business trust by her/himself as a such officer Trinity Rail Leasing Trust II.

WITNESS my hand and official seal this 28th day of October, 2002.

MY COMMISSION EXPIRES: 1/28/64

Notary Public Patricia a. Sheess

PATRICIA A. THEISS
Notary Public, State of Texas
My Commission Expires
01/28/2004

ACKNOWLEDGMENT

STATE OF	New	York)
COUNTY OF	Kin)

BEFORE ME, a Notary Public of the State and County aforesaid, personally appeared Mark Langel forest Joane, who upon oath, acknowledged himself to be a View fresident of CREDIT SUISSE FIRST BOSTON, NEW YORK BRANCH, and that s/he as such officer being authorized to do so, executed the foregoing Memorandum of Security Agreement for the purposes therein contained by signing the name of such bank by her/himself as a such officer such Credit Suisse First Boston, New York Branch.

WITNESS my hand and official seal this 28th day of October, 2002.

Vinen - P. Sel. Notary Public

MY COMMISSION EXPIRES: 15/25/02

Vivienne I. Bent Notary Public, State of New York No. 01 BE6050122 Qualified in Kings County Commission Expires October 30, 2002

EXHIBIT A

to Memorandum of Security Agreement

RAILCARS

[see attached]

RAILCARS

Car Mark	Car Number						
ACTX	210021	ARJX	260967	TILX	190426	TILX	200230
ACTX	210022	ARJX	260971	TILX	190429	TILX	200231
ACTX	210023	ARJX	260990	TILX	190432	TILX	200232
ACTX	210024	ARJX	260991	TILX	190433	TILX	200233
ACTX	210025	ARJX	260992	TILX	190434	TILX	200234
ACTX	210026	ARJX	260993	TILX	190439	TILX	200235
ACTX	210027	ARJX	260996	TILX	200194	TILX	200236
ACTX	210028	TILX	110105	TILX	200195	TILX	200237
ACTX	210029	TILX	110106	TILX	200196	TILX	200238
ACTX	210030	TILX	110090	TILX	200197	TILX	200239
ACTX	210031	TILX	110091	TILX	200198	TILX	250324
ACTX	210032	TILX	110092	TILX	200199	TILX	250325
ACTX	210033	TILX	110093	TILX	200200	TILX	250326
ACTX	210034	TILX	110094	TILX	200201	TILX	250327
ARJX	210035	TILX	110095	TILX	200202	TILX	250328
ARJX	210036	TILX	110096	TILX	200203	TILX	250329
ARJX	210037	TILX	110097	TILX	200204	TILX	250330
ARJX	210038	TILX	110098	TILX	200205	TILX	250331
ARJX	210039	TILX	110099	TILX	200206	TILX	250332
ARJX	210040	TILX	110100	TILX	200207	TILX	250333
ARJX	210041	TILX	110101	TILX	200208	TILX	250334
ARJX	210042	TILX	110102	TILX	200209	TILX	250335
ARJX	210043	TILX	110103	TILX	200210	TILX	250336
ARJX	210044	TILX	110104	TILX	200211	TILX	250337
ARJX	260949	TILX	190398	TILX	200212	TILX	250338
ARJX	260950	TILX	190402	TILX	200213	TILX	250339
ARJX	260951	TILX	190403	TILX	200214	TILX	250340
ARJX	260952	TILX	190404	TILX	200215	TILX	250341
ARJX	260953	TILX	190405	TILX	200216	TILX	250342
ARJX	260954	TILX	190406	TILX	200217	TILX	250343
ARJX	260955	TILX	190407	TILX	200218	TILX	250344
ARJX	260956	TILX	190408	TILX	200219	TILX	250345
ARJX	260957	TILX	190409	TILX	200220	TILX	250346
ARJX	260958	TILX	190410	TILX	200221	TILX	250347
ARJX	260959	TILX	190411	TILX	200222	TILX	250348
ARJX	260960	TILX	190412	TILX	200223	TILX	250349
ARJX	260961	TILX	190413	TILX	200224	TILX	250350
ARJX	260962	TILX	190417	TILX	200225	TILX	250351
ARJX	260963	TILX	190422	TILX	200226	TILX	260925
ARJX	260964	TILX	190423	TILX	200227	TILX	260926
ARJX	260965	TILX	190424	TILX	200228	TILX	260927
ARJX	260966	TILX	190425	TILX	200229	TILX	260928

RAILCARS

Car Number	Car Mark	Car Number	Car Mark	Car Number	Car Mark	Car Number
260929	TILX	301957	TILX	302087	TILX	302154
260930	TILX	301958	TILX	302088	TILX	302155
260931	TILX	301959	TILX	302089	TILX	302156
260932	TILX	301960	TILX	302090	TILX	302157
260933	TILX	301961	TILX	302091	TILX	302158
260934	TILX	301962	TILX	302092		302159
260935	TILX	301963	TILX			302160
260936	TILX	301964	TILX	302094	TILX	302161
260937	TILX	301965	TILX	302095	TILX	302162
260938	TILX	302054	TILX	302096		302163
260939	TILX	302055	TILX	302097	TILX	302164
260940	TILX	302056	TILX	302098	TILX	302165
260941	TILX	302057	TILX	302099	TILX	302166
260942	TILX	302058	TILX	302100	TILX	302167
260943	TILX	302059	TILX	302101		302168
260944	TILX	302060	TILX	302102	TILX	302169
260945	TILX	302061	TILX	302103	TILX	302170
260946	TILX	302062	TILX	302104	TILX	302171
260947	TILX	302063	TILX	302105	TILX	302172
260948	TILX	302064	TILX	302106		302173
261096	TILX	302065	TILX	302107	TILX	302174
261097	TILX	302066	TILX	302108	TILX	302175
261098	TILX	302067	TILX	302109	TILX	302176
301938	TILX	302068	TILX	302110	TILX	302177
301939	TILX	302069	TILX	302111	TILX	302178
301940	TILX	302070	TILX	302112	TILX	302179
301941	TILX	302071	TILX	302113	TILX	302180
301942	TILX	302072	TILX	302114		302181
301943	TILX	302073	TILX	302115		302182
301944	TILX	302074	TILX	302116	TILX	302183
301945		302075	TILX	302117	TILX	302184
301946	TILX	302076	TILX	302118		302185
301947	TILX	302077	TILX	302119	TILX	302186
301948	TILX	302078	TILX		TILX	302187
301949	TILX	302079	TILX	302121		302188
301950	TILX	302080	TILX	302122		302189
301951	TILX	302081	TILX	302123	TILX	302190
301952	TILX	302082	TILX	302124	TILX	302191
301953	TILX	302083	TILX	302125	TILX	302192
301954	TILX	302084	TILX	302126	TILX	302193
301955	TILX	302085	TILX	302127	TILX	302194
301956	TILX	302086	TILX	302128	TILX	302195
	260929 260930 260931 260932 260933 260934 260935 260936 260937 260938 260940 260941 260942 260943 260945 260946 260947 260948 261096 261097 261098 301938 301939 301940 301941 301942 301943 301944 301945 301946 301947 301948 301947 301948 301950 301951 301952 301953 301955	260929 TILX 260930 TILX 260931 TILX 260932 TILX 260933 TILX 260934 TILX 260935 TILX 260936 TILX 260937 TILX 260938 TILX 260939 TILX 260940 TILX 260941 TILX 260942 TILX 260943 TILX 260944 TILX 260945 TILX 260946 TILX 260947 TILX 261096 TILX 261097 TILX 301938 TILX 301938 TILX 301940 TILX 301941 TILX 301942 TILX 301943 TILX 301944 TILX 301945 TILX 301946 TILX 301947 TILX 301948 </td <td>260929 TILX 301957 260930 TILX 301958 260931 TILX 301959 260932 TILX 301960 260933 TILX 301961 260934 TILX 301962 260935 TILX 301963 260936 TILX 301964 260937 TILX 301965 260938 TILX 302054 260939 TILX 302054 260939 TILX 302055 260940 TILX 302056 260941 TILX 302057 260942 TILX 302058 260943 TILX 302061 260944 TILX 302062 260945 TILX 302062 260947 TILX 302062 260948 TILX 302064 261097 TILX 302066 261098 TILX 302066 261098 TILX 302068 <td>260929 TILX 301957 TILX 260930 TILX 301958 TILX 260931 TILX 301959 TILX 260932 TILX 301960 TILX 260933 TILX 301961 TILX 260934 TILX 301962 TILX 260935 TILX 301963 TILX 260936 TILX 301964 TILX 260937 TILX 301965 TILX 260938 TILX 302054 TILX 260939 TILX 302055 TILX 260940 TILX 302055 TILX 260941 TILX 302057 TILX 260942 TILX 302058 TILX 260943 TILX 302065 TILX 260944 TILX 302060 TILX 260945 TILX 302061 TILX 260946 TILX 302063 TILX 261097 T</td><td>260929 TILX 301957 TILX 302087 260930 TILX 301958 TILX 302088 260931 TILX 301959 TILX 302089 260932 TILX 301960 TILX 302090 260933 TILX 301961 TILX 302091 260934 TILX 301962 TILX 302092 260935 TILX 301963 TILX 302094 260936 TILX 301964 TILX 302094 260937 TILX 301965 TILX 302095 260938 TILX 302054 TILX 302096 260939 TILX 302055 TILX 302097 260940 TILX 302055 TILX 302099 260941 TILX 302057 TILX 302099 260942 TILX 302058 TILX 302100 260944 TILX 302066 TILX 302102 <t< td=""><td>260929 TILX 301957 TILX 302087 TILX 260930 TILX 301958 TILX 302088 TILX 260931 TILX 301959 TILX 302089 TILX 260932 TILX 301960 TILX 302090 TILX 260933 TILX 301961 TILX 302091 TILX 260934 TILX 301962 TILX 302092 TILX 260936 TILX 301963 TILX 302093 TILX 260936 TILX 301964 TILX 302095 TILX 260937 TILX 301965 TILX 302096 TILX 260938 TILX 302055 TILX 302097 TILX 260939 TILX 302055 TILX 302097 TILX 260940 TILX 302056 TILX 302097 TILX 260941 TILX 302057 TILX 302101 TILX</td></t<></td></td>	260929 TILX 301957 260930 TILX 301958 260931 TILX 301959 260932 TILX 301960 260933 TILX 301961 260934 TILX 301962 260935 TILX 301963 260936 TILX 301964 260937 TILX 301965 260938 TILX 302054 260939 TILX 302054 260939 TILX 302055 260940 TILX 302056 260941 TILX 302057 260942 TILX 302058 260943 TILX 302061 260944 TILX 302062 260945 TILX 302062 260947 TILX 302062 260948 TILX 302064 261097 TILX 302066 261098 TILX 302066 261098 TILX 302068 <td>260929 TILX 301957 TILX 260930 TILX 301958 TILX 260931 TILX 301959 TILX 260932 TILX 301960 TILX 260933 TILX 301961 TILX 260934 TILX 301962 TILX 260935 TILX 301963 TILX 260936 TILX 301964 TILX 260937 TILX 301965 TILX 260938 TILX 302054 TILX 260939 TILX 302055 TILX 260940 TILX 302055 TILX 260941 TILX 302057 TILX 260942 TILX 302058 TILX 260943 TILX 302065 TILX 260944 TILX 302060 TILX 260945 TILX 302061 TILX 260946 TILX 302063 TILX 261097 T</td> <td>260929 TILX 301957 TILX 302087 260930 TILX 301958 TILX 302088 260931 TILX 301959 TILX 302089 260932 TILX 301960 TILX 302090 260933 TILX 301961 TILX 302091 260934 TILX 301962 TILX 302092 260935 TILX 301963 TILX 302094 260936 TILX 301964 TILX 302094 260937 TILX 301965 TILX 302095 260938 TILX 302054 TILX 302096 260939 TILX 302055 TILX 302097 260940 TILX 302055 TILX 302099 260941 TILX 302057 TILX 302099 260942 TILX 302058 TILX 302100 260944 TILX 302066 TILX 302102 <t< td=""><td>260929 TILX 301957 TILX 302087 TILX 260930 TILX 301958 TILX 302088 TILX 260931 TILX 301959 TILX 302089 TILX 260932 TILX 301960 TILX 302090 TILX 260933 TILX 301961 TILX 302091 TILX 260934 TILX 301962 TILX 302092 TILX 260936 TILX 301963 TILX 302093 TILX 260936 TILX 301964 TILX 302095 TILX 260937 TILX 301965 TILX 302096 TILX 260938 TILX 302055 TILX 302097 TILX 260939 TILX 302055 TILX 302097 TILX 260940 TILX 302056 TILX 302097 TILX 260941 TILX 302057 TILX 302101 TILX</td></t<></td>	260929 TILX 301957 TILX 260930 TILX 301958 TILX 260931 TILX 301959 TILX 260932 TILX 301960 TILX 260933 TILX 301961 TILX 260934 TILX 301962 TILX 260935 TILX 301963 TILX 260936 TILX 301964 TILX 260937 TILX 301965 TILX 260938 TILX 302054 TILX 260939 TILX 302055 TILX 260940 TILX 302055 TILX 260941 TILX 302057 TILX 260942 TILX 302058 TILX 260943 TILX 302065 TILX 260944 TILX 302060 TILX 260945 TILX 302061 TILX 260946 TILX 302063 TILX 261097 T	260929 TILX 301957 TILX 302087 260930 TILX 301958 TILX 302088 260931 TILX 301959 TILX 302089 260932 TILX 301960 TILX 302090 260933 TILX 301961 TILX 302091 260934 TILX 301962 TILX 302092 260935 TILX 301963 TILX 302094 260936 TILX 301964 TILX 302094 260937 TILX 301965 TILX 302095 260938 TILX 302054 TILX 302096 260939 TILX 302055 TILX 302097 260940 TILX 302055 TILX 302099 260941 TILX 302057 TILX 302099 260942 TILX 302058 TILX 302100 260944 TILX 302066 TILX 302102 <t< td=""><td>260929 TILX 301957 TILX 302087 TILX 260930 TILX 301958 TILX 302088 TILX 260931 TILX 301959 TILX 302089 TILX 260932 TILX 301960 TILX 302090 TILX 260933 TILX 301961 TILX 302091 TILX 260934 TILX 301962 TILX 302092 TILX 260936 TILX 301963 TILX 302093 TILX 260936 TILX 301964 TILX 302095 TILX 260937 TILX 301965 TILX 302096 TILX 260938 TILX 302055 TILX 302097 TILX 260939 TILX 302055 TILX 302097 TILX 260940 TILX 302056 TILX 302097 TILX 260941 TILX 302057 TILX 302101 TILX</td></t<>	260929 TILX 301957 TILX 302087 TILX 260930 TILX 301958 TILX 302088 TILX 260931 TILX 301959 TILX 302089 TILX 260932 TILX 301960 TILX 302090 TILX 260933 TILX 301961 TILX 302091 TILX 260934 TILX 301962 TILX 302092 TILX 260936 TILX 301963 TILX 302093 TILX 260936 TILX 301964 TILX 302095 TILX 260937 TILX 301965 TILX 302096 TILX 260938 TILX 302055 TILX 302097 TILX 260939 TILX 302055 TILX 302097 TILX 260940 TILX 302056 TILX 302097 TILX 260941 TILX 302057 TILX 302101 TILX

RAILCARS

Car Mark	Car Number						
TILX	302196	TILX	302258	TIMX	291030	TIMX	291072
TILX	302197	TILX	302259	TIMX	291031	TIMX	291073
TILX	302198	TILX	400593	TIMX	291032	TIMX	291074
TILX	302199	TILX	400594	TIMX	291033		
TILX	302200	TILX	400595	TIMX	291034		
TILX	302201	TILX	400596	TIMX	291035		
TILX	302202	TILX	400597	TIMX	291036		
TILX	302203	TILX	400598	TIMX	291037		
TILX	302224	TILX	400599	TIMX	291038		
TILX	302225	TILX	400600	TIMX	291039		
TILX	302226	TILX	400601	TIMX	291040		
TILX	302227	TILX	400602	TIMX	291041		
TILX	302228	TIMX	291000	TIMX	291042		
TILX	302229	TIMX	291001	TIMX	291043		
TILX	302230	TIMX	291002	TIMX	291044		
TILX	302231	TIMX	291003	TIMX	291045		
TILX	302232	TIMX	291004	TIMX	291046		
TILX	302233	TIMX	291005	TIMX	291047		
TILX	302234	TIMX	291006	TIMX	291048		
TILX	302235	TIMX	291007	TIMX	291049		
TILX	302236	TIMX	291008	TIMX	291050		
TILX	302237	TIMX	291009	TIMX	291051		
TILX	302238	TIMX	291010	TIMX	291052		
TILX	302239	TIMX	291011	TIMX	291053		
TILX	302240	TIMX	291012	TIMX	291054		
TILX	302241	TIMX	291013	TIMX	291055		
TILX	302242	TIMX	291014	TIMX	291056		
TILX	302243	TIMX	291015	TIMX	291057		
TILX	302244	TIMX	291016	TIMX	291058		
TILX	302245	TIMX	291017	TIMX	291059		
TILX	302246	TIMX	291018	TIMX	291060		
TILX	302247	TIMX	291019	TIMX	291061		
TILX	302248	TIMX	291020	TIMX	291062		
TILX	302249	TIMX	291021	TIMX	291063		
TILX	302250	TIMX	291022	TIMX	291064		
TILX	302251	TIMX	291023	TIMX	291065		
TILX	302252	TIMX	291024	TIMX	291066		
TILX	302253	TIMX	291025	TIMX	291067		
TILX	302254	TIMX	291026	TIMX	291068		
TILX	302255	TIMX	291027	TIMX	291069		
TILX	302256	TIMX	291028	TIMX	291070		
TILX	302257	TIMX	291029	TIMX	291071		

EXHIBIT B

to Memorandum of Security Agreement

LEASES

[see attached]

LEASES

<u>Lessees</u>	Riders
333	1
333	2
502	1
796	3
796	4
832	5
3016	1
3601	1
5550	1
5015	8
6552	1
7440	1
8385	2
8385	3
4859	5
8384	3